

Frame Bound Surveys

Roof Survey Report



Harlesden Court

17th March 2022

Revision	Date	Author
P01	17/03/2022	HA

17th March 2022 FSU0002 Harlesden Court



Summary


Aerial photo shows gutter blockage due to build up of waste over time. In addition to this debris and waste build up has been identified.

Keys



Moderate Condition - Highlighted area will require corrective action to reduce any further deterioration and assure proper reliable function of component

Poor Condition - Highlighted area requires immediate extensive repair works or replacement





oof Plan





Reference #	Issue	Description	Page
01	Damaged membrane	Damaged membrane due to cable antenna cable route	06
02	Debris	Built up of debris and waste	06
03	Debris	Built up of debris and waste	07
04	Gutter blockage	Gutter blockage due to build up of debris and waste	07
05	Waste	Discarded cast iron pipe on roof	08
06	Gutter blockage	Gutter blockage due to build up of debris and waste	09





Damaged membrane due to antenna cable route. Further observation on joint required to determine impact.



Build up of debris and waste on roof.





#03


Build up of debris and waste



#04

Gutter blockage as a result of debris and waste. Requires cleaning of gutter





Discard cast iron pipe left on roof





#06

Gutter blockage as a result of waste and debris build up

ference #	Issue	Description	Page
07	Rain water build up	Unlevel surface resulting in rain water ponding	11





#07

Unlevel surface causing rain water ponding