

Frame Bound Surveys

Roof Survey Report



Retail Park

2nd April 2022

Date	Author
02/04/2022	HA

2nd April 2022

FSU0008

Retail Park




Summary

Holes on the roof has been observed in highlighted locations which require immediate attention and repair work.

Keys

- Good Condition Highlighted area requires cleaning, painting, minor repair works
- Moderate Condition Highlighted area will require corrective action to reduce any further deterioration and assure proper reliable function of component
- Poor Condition Highlighted area requires immediate extensive repair works or replacement





0 0 2

oof Plan 0 2





Reference #	Issue	Description	Page
01	Damaged joint	Damaged/bent joint between panels	07







Reference #	Issue	Description	Page
02	Exposed hole	Exposed hole/opening through roof	09
03	Exposed hole	Significant damage to roof	10
04	Exposed hole	Exposed hole/opening through roof	11
05	Damaged roof glass	Damaged roof glass	12













#04

Exposed hole/opening through roof





Damaged roof glass